

STATUS OF THE CLAIMS

Claims 1-16 are pending. Claims 9, 11 and 14 have been amended.

REMARKS

Pursuant to 37 CFR § 1.121, the above amendments are marked on separate sheets entitled "VERSION WITH MARKINGS TO SHOW CHANGES MADE" following these remarks.

The specification in column 1, line 63 has been amended by replacing the erroneous recitation of "valve 12a" with -- valve 12b --. Support for this amendment can be found in FIG. 1C which shows fluid (depicted by the bolded arrow) entering the valve assembly 10 through valve 16a and exiting the valve assembly 10 through valve 12b. Hence, no new matter is believed entered by this amendment.

The specification in column 3, line 21 has been amended by replacing the erroneous recitation of "A-A" with -- 3B-3B --. Support for this amendment can be found in FIG. 3A which shows only the section line 3B-3B. Hence, no new matter is believed entered by this amendment.

The specification in column 4, lines 16-19 has been amended by replacing the erroneous recitation "Fluid entering any of the ports encounters a chamber and channels leading to three diverter valves." with -- Fluid entering any of the ports encounters a chamber and channels leading to *at least two* diverter valves. *Fluid entering port 52, for example, encounters chamber 62 and channels leading to diverter valves 70 and 72.* -- Support for this amendment can be found in FIG. 3A. Hence, no new matter is believed entered by this amendment.

The specification in column 4, line 30 has been amended by replacing the erroneous

recitation of "A-A" with -- 3B-3B --. Support for this amendment can be found in FIG. 3A which shows only the section line 3B-3B. Hence, no new matter is believed entered by this amendment.


Claims 9 and 11 have been amended to correct typographical/spelling errors. In particular, the term "exists" recited in claims 9 and 11 has been replaced with the term -- exits --. Support for these amendments can be found in column 4, lines 19-59. Hence, no new matter is believed entered by this amendment.

Claim 14 has been amended to correct indefiniteness in the recitation of "between third and said second chamber." In particular, the definite article "said" was inadvertently omitted between the terms "between" and "third" in this recitation. Since the "third chamber" element is positively recited for the first time in claim 1, from which claim 14 indirectly depends, the definite article "said" should have been recited between the terms "between" and "third" in claim 14 to refer back to the "third chamber." No new matter is believed entered by this amendment.

It is respectfully submitted that claims 1-16 are in condition for allowance, early notification of which is earnestly solicited. Should there be any questions or other matters whose resolution may be advanced by a telephone call, the Examiner is cordially invited to contact Applicant's undersigned attorney at his number listed below.

No fee is believed due as a result of this communication. The Commissioner, however, is hereby authorized to charge any other fees which may be required or credit any overpayment to Deposit Account No. 04-1679.

Respectfully submitted,



Paul A. Schwarz, Esq.
Reg. No. 37,577

Duane, Morris & Heckscher LLP
100 College Road West, Suite 100
Princeton, New Jersey 08540
(609) 919-4408
(609) 919-4401 - facsimile

VERSION WITH MARKINGS TO SHOW CHANGES MADE

The following marked-up specification and claims correspond to the replacement specification and claims of this amendment.

Last paragraph starting at line 46 of column 1:

Fluid can flow through the prior art valve assembly 10 depicted in FIG. 1A in any one of the three directions depicted in FIGS. 1B-1D. The fluid flow is represented by arrows 25 in these figures. In FIG. 1B, which represents the forward product flow through the column, valve 14a is opened allowing the fluid to flow from the process piping into the valve assembly 10. Valve 16a is also opened allowing the fluid to flow into the chromatography column (not shown). The fluid returns from the chromatography column passing through valve 16b and reentering the valve assembly. The fluid leaves the valve assembly passing through valve 14b on its path back to the process piping. Valves 12a and 12b remain closed during this process. According to the reverse process flow depicted in FIG. 1C, fluid entering the valve assembly 10 from the process piping can flow through valves 12a and 16b into the column, returning from the column through valve 16a, and exiting the valve assembly through valve [12a] 12b back through the process piping. Valves 14a and 14b remain closed during this process. The column may be bypassed altogether according to the process flow depicted in FIG. 1D, where the liquid entering into the valve assembly from the process piping encounters opened valves 12a, 14a, 12b and 14b, exiting the valve assembly without entering the chromatography column which remains inaccessible by closing valves 16a and 16b.

The fifth full paragraph of column 3 starting at line 20:

FIG. 3B is an enlarged cross-sectional view through line [A-A] 3B-3B of FIG. 3A;

The first full paragraph of column 4 starting at line 6:

Referring now to FIG. 3A, there is shown a top view of the valve assembly, minus the manual bonnets and with a partial cross-sectional view of the underlying channel network drawn in with broken lines. As can be seen in this figure, ports 50, 52, 54 and 56 are arranged at angles of approximately 90° with respect to each other on opposing ends of the octagonal base section of the valve assembly. Each port opens into a chamber in the valve assembly 30—port 50 opening into chamber 60, port 52 opening into chamber 62, port 54 opening into chamber 64, and port 56 opening into chamber 66. Fluid entering any of the ports encounters a chamber and channels leading to [three] at least two diverter valves. Fluid entering port 52, for example, encounters chamber 62 and channels leading to diverter valves 70 and 72. Fluid entering port 50, for example, encounters chamber 60 and channels leading to diverter valves 70, 76 and 78. The smooth and tortuous network of passageways that lead through the valve assembly connect the ports with the chambers and valves in a such a way that the valve assembly is fully drainable as will be later explained. The flow of the fluid is controlled by the diverter valves 70, 72, 74, 76, 78 and may be adjusted to permit specific flow directions which, in combination with the smooth and tortuous passageways, eliminate dead-legs from the system.

The second full paragraph of column 4 starting at line 28:

Referring now to FIG. 3B, there is shown an enlarged cross-sectional view of the valve

assembly through line [A-A] 3B-3B of FIG. 3A. As can be seen in the figure, port 50 opens into chamber 60. A passageway 55 leading to diverter valve 76 can also be seen in this figure.

Chamber 60 is connected to chamber 64 via diverter valve 78. The passageway that connects these two chambers is inclined, rising sharply before encountering diverter valve 78 and then falling sharply after encountering the valve. The angle of inclination 63 measured from either side of the diverter valve 78 is approximately 30°. In chamber 64, a passageway 65 leading to diverter valve 74 can be seen. Finally in this figure, port 54 can be seen as opening into chamber 64.

9.(AMENDED) The diverter valve assembly of claim 1, wherein fluid flowing in a first direction enters said valve assembly through said first port, passes through said first chamber, is directed across said first diverter valve into said second chamber, exits said valve assembly through said second port, reenters said valve assembly through said fourth port, passes through said fourth chamber, is directed across said third diverter valve, passes through said third chamber, and [exists] exits said valve assembly through said third port.

11.(AMENDED) The diverter valve assembly of claim 1, wherein fluid flowing in a second direction enters said valve assembly through said first port, passes through said first chamber, is directed across said fourth diverter valve into said fourth chamber, exits said valve assembly through said fourth port, reenters said valve assembly through said second port, passes through said second chamber, is directed across said second diverter valve, passes through said third chamber, and [exists] exits said valve assembly through said third port.

14.(AMENDED) The diverter valve assembly of claim 13, wherein said first diverter valve operates to prevent fluid communication between said first and said second chamber, said second diverter valve operates to prevent fluid communication between said third and said second chamber, said fourth diverter valve operates to prevent fluid communication between said third and said fourth chamber, and said fourth diverter valve operates to prevent fluid communication between said first and said fourth chamber.

11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
841
842
843
844
845
846
847
848
849
850
851
852
853
854
855
856
857
858
859
860
861
862
863
864
865
866
867
868
869
870
871
872
873
874
875
876
877
878
879
880
881
882
883
884
885
886
887
888
889
890
891
892
893
894
895
896
897
898
899
900
901
902
903
904
905
906
907
908
909
910
911
912
913
914
915
916
917
918
919
920
921
922
923
924
925
926
927
928
929
930
931
932
933
934
935
936
937
938
939
940
941
942
943
944
945
946
947
948
949
950
951
952
953
954
955
956
957
958
959
960
961
962
963
964
965
966
967
968
969
970
971
972
973
974
975
976
977
978
979
980
981
982
983
984
985
986
987
988
989
990
991
992
993
994
995
996
997
998
999
1000